

Blue Heron Stain Grey Blue Prod # 467983



MATERIAL SAFETY DATA SHEET

SUPPLIER:

SINOPIGMENT & ENAMEL CHEMICALS LTD

ADD: DANFENG SOUTH RD. WUJIAXIANG INDUSTRIAL PARK, XIANGTAN COUNTY, HUNAN PROV. CHINA

TEL: 86-732-7805588 FAX: 7805688

City of Industry, CA 91746 1-800-4Laguna info@lagunaclay.com www.lagunaclay.com

PRODUCT INDENTIFICATION:

PRODUCT NAME CERAMIC STAIN

II. HAZARDOUS INGREDIENTS:

This product contains no hazardous ingredients.

III. PHYSICAL AND CHEMICAL PROPERTIES:

PHYSICAL FORM Solid, Powder

COLORGrey

AVERAGE PARTICLE SIZE...............0.5%max (325mesh residue on sieve)

IV. FIRE AND EXPLOSION DATA:

FLASH POINT Not applicable

AUTO- IGNITION TEMPERATURE Not Applicable

EXTINGUISHING MEDIA...... Material is not combustible. Use

extinguishing media suitable for other

combustible materials in the area.

SPECIAL FIRE FIGHTING PROCEDURES. None

V. HUMAN HEALTH DATA:

ROUTE(S) OF ENTRY Eye contact; Skin contact; Inhalation

HUMAN EFFCTS AND SYMPTOMS OF OVEREXPOSURE:

On the basis of Animal Toxicity Data, we would expect this product to be

MSDS Page 1 Continued on next page



non-irritating to the eyes and skin and essentially non-toxic by ingestion.

However, excessive exposure to airborne dust may reduce visibility and/or cause unpleasant deposits in the eyes, ears, and nose. Injury to the skin or mucous membranes can occur by direct mechanical action or by rigorous skin cleaning necessary for removal of dust.

known from repeated exposure to this stain.

VI. EMERGENCY AND FIRST AID PROCEDURES:

REMOVE FROM EXPOSURE

- FIRST AID FOR EYES Flush eyes with plenty of water, lifting lids periodically for at least 15 minutes. Consult a physician taking this data sheet if redness or soreness develops.
- with soap and water.
- FIRST AID FOR INHALATION Symptomatic treatment. Remove from dusty area to fresh air. If not breathing, give artificial respiration. If breathing is difficult, gives oxygen, call a physician.
- FIRST AID FOR INGESTIONDrink water and induce vomiting. Immediately contact a physician.

IF THESE FIRST AID MEASURES FAIL, CONSULT PHYSICIAN !!!!!!!!!!

VII. EMPLOYEE PROTECTION RECOMMENDATIONS:

- EYES PROTECTION REQUIREMENTS Safety glasses are recommended.
- SKIN PROTECTION REQUIREMENTSWear easily washable work clothing, Wear normal industrial protective clothing, i.e. overalls, gloves and goggles. Protect from dust, wash after use.
- RESPIRATOR REQUIREMENTSAmbient concentrations in the work area should be monitored and if the recommended exposure limit is exceeded, a NIOSH/MSHA approved dust respirator should be worn.
- air level below the recommended exposure limit if dusting is a problem.
- ADDITIONAL PROTECTIVE MEASURES Eyewash stations and washing facilities should be available. Employees should wash their hands and face before eating, drinking or using tobacco products.

MSDS Page 2 Continued on next page



VIII. SPILL AND LAEK PROCEDURES:

SPILL OR LEAK PROCEDURES......Vacuum or scoop material into an appropriately marked container for reclamation or disposal. Avoid excessive generation of dust. If dust is generated, use appropriate respiratory protection.

WASTE DISPOSAL METHODSMaterials, which cannot be recycled into your process should be land filled in accordance with federal, state and local environment control regulations.

IX. SPECIAL PRECAUTIONS AND STORAGE DATA:

STORAGE TEMPERATURE (MIN/MAX)...Ambient /Ambient

HANDLING STORAGE PRECAUTIONS. : Store in dry at ambient temperature, away from food and beverages. Avoid breathing dust. Avoid contact with eyes and skin, wash thoroughly after handling.

This information is furnished without warranty, expressed or implied, except that it is accurate to the best knowledge of Sinopigment & Enamel Chemicals Ltd. The date on this sheet relates only to the specific material designated herein. Sinopigment & Enemal Chemicals Ltd assumes no legal responsibility for use or reliance upon these data.



MSDS Page 3 Last page